



Matereality Tips & Tricks

Create CAE Master Material files for use in HyperWorks

- 1. Open your Matereality CAE Models library
 - a. Select CAE material model files you want to use
 - b. Click the Altair HyperWorks button to export the selected items as a zip file
 - c. Save the zip file to your computer and extract all files
 - d. Run the **Import into HyperWorks** batch file included in the zip file
 - e. Give the library a name, and select the folder that contains your HyperWorks Master Material models
- 2. View your Master Material model files within the HyperMesh Organize browser

Now you can assign the material to a part and select the desired solver to complete your analysis.